

Oil Field Environmental Incident Summary

Incident: 20160108134825 **Date/Time of Notice:** 01/08/2016 13:48

Responsible Party: HESS CORPORATION

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: RUSSELL E. SMITH 24-43H

Field Name: CAPA

Well File #: 15832

Date Incident: 1/7/2016

Time Incident: 17:30

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 96

Sec: 24

Qtr: SW SE

Location Description:

Submitted By: Alex Beach

Received By:

Contact Person: Troy Brunsell
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2000 Feet

Distance Nearest Water Well: 2000 Feet

Type of Incident: Treater Popoff

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	barrels
Brine					0	barrels
Other	1.1	Barrels			1.3	barrels

Description of Other Released Contaminant:

Emsulsion

Inspected:

Written Report Received: 1/28/2016

Clean Up Concluded: 1/26/2016

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

125' by 77.5' (total) 65' by 57.5' total

Potential Environmental Impacts:

There are potential environmental impacts to the 65' by 57.5' area offsite.

Action Taken or Planned:

Arrangements will be made to have the impacted areas remediated. The landowner will be notified of the release.

Wastes Disposal Location: The impacted material will be cleaned up and disposed of at an approved waste disposal facility.

Agencies Involved:**Updates**

Date: 1/8/2016 **Status:** Reviewed - Follow-up Required **Author:** Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained. Further followup is necessary.

Date: 1/13/2016 **Status:** Inspection **Author:** Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/13/2016 at 15:20, on location. Affected area southeast of treater unit on eastern edge of wellpad. Upward slope bordering wellpad to east was impacted; shows evidence of being scraped. Some faint staining by One-Call markings, but snow around fenceline to the east of the wellpad has no visible staining.

Date: 7/26/2016 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

7/26/2016 at 15:37, on location. Scraped area is now vegetated. No further follow-up required.